



Norman H. Bangarter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: August 29, 1989  
2:00 p.m. to 5:00 p.m.

Permittee and/or Operators Name: Genwal Coal Company  
Business Address: P.O. Box 1201, Huntington, Utah 84527  
Mine Name: Crandall Canyon Permit Number: ACT/015/032  
Type of Mining Activity: Underground XX Surface Other  
County: Emery  
Company Official (s): Allen Childs  
State Official(s): Harold G. Sandbeck and Sue Linner  
Partial: XXX Complete:        Date of Last Inspection: July 27, 1989  
Weather Conditions: Clear and warm  
Acreage: Permitted 164.4 Disturbed 5.75 Regraded 0.5 Seeded 0.5 Bonded 5.75  
Enforcement Action:       

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	(XX )	( )	( )	( )
3. TOPSOIL	( )	(XX )	( )	(XX )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(XX )	( )	( )	( )
b. DIVERSIONS	(XX )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	(XX )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	(XX )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION 8/29/89

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments. On this partial inspection, the undersigned inspector was accompanied by Alan Childs (Operator's Environmental Engineer). Ground conditions were relatively dry.

3. Topsoil.

N89-27-9-1

N89-27-9-1 was issued on July 27, 1989 for failure to comply with the approved plan. SAE 4 and SAE 7 requires installation of treatment controls as described in the plan on pages 7-72 and 7-72b. The operator had complied with the first part of the remedial action section by placing treatment control measures along the toe of the outslope at SAE 4 before the August 14, 1989 deadline. As of August 29, 1989, the operator was waiting for a shipment of straw bales to abate the above mentioned violation. The abatement date for the above mentioned violation is September 8, 1989 at 5:00 p.m.

Copy of this Report:

Mailed to: Allen Childs (Genwal Coal), Price Office and Brian Smith(OSM)

Given to: Sue Linner and Joe Helfrich - DOGM

Inspectors Signature and Number: *Harold D. Smith* #27 Date: 9/5/89